




# Pyranometer Mount #16073 | Square Torque Tube

## Introduction

Kit #16073 is designed to mount a pyranometer to a 6-inch square torque tube using Universal Mounting Plate #15498 and a sandwich plate assembly. The mount can be attached to square tubing sized down to 3.5 inches and up to a maximum size of 6 inches. This mount also provides plate isolation via nylon hardware for improved protection of the pyranometer from electrostatic discharge.




## #16073: Parts/BOM


NRG Part Number	Part Description	Part Specification Notes	Qty	Diagram Key
15821	Angle Bracket	Pre-drilled angled aluminum	2	1
14980	Button Head Screw	5/16-18 thread   0.875" length   Stainless	2	4
14979	Nyloc Nut	5/16-18 thread   Stainless	2	5
12022	Button Head Screw	1/4-20 thread   0.75" length   Stainless	2	2
15869	Serrated Flange Locknut	1/4-20 thread   Stainless	2	3
14397	Mounting Screws	M5 x 0.8   10mm length   Stainless	2	8
15498	Mounting Plate	Aluminum   3/16" thickness	1	9
16091	Sandwich Plate	Aluminum   0.19" thickness   Pre-drilled	1	6
17245	Mounting Bolts	3/8-16 full-thread   7" length   Stainless	2	10
16101	Mounting Nuts	3/8-16 thread   Stainless	2	7
12095	Washers	3/8" ID   Stainless	4	11
18249	Nylon washers	Washer, Nylon, .34 ID	2	
18250	Nylon washers	Washer, Nylon, .375 ID	2	
18251	Nylon sleeve washer	Washer, Sleeve, Nylon, .3125 ID	2	



Tools



Procedure







## Pyranometer Mount #16073 | Square Torque Tube

Refer to the diagram on the previous page.

1. Attach Universal Pyranometer Mounting Plate (#15498) to one angle bracket (#15821) with the 5/16-18 stainless hardware as described below and shown in step 1 of the Procedure numbered diagram above.
  - Insert the screws (#14980) into the sleeve washers (#18251) and then through the holes in the pyranometer mounting plate (#15498). Add nylon washers (#18250) to the ends of the screws, and insert the screws through the holes in the angle bracket (#15821). Add nylon washers (#18249) to the ends of the screws before adding the nuts (#14979) as shown below. Nylon sleeve washer and disc washers are represented in blue.



2. Attach both angle brackets together with the 1/4-20 stainless bolt (#12022) and nut (#15869) hardware. Leave slightly loose for final adjustment at the end.



## Pyranometer Mount #16073 | Square Torque Tube

3. Remove the pyranometer feet. The sensor is secured directly to the pyranometer mounting plate.
4. Attach the pyranometer to plate (#15498) using the M5 stainless hardware (#14397).



***Apply a small amount of anti-seize to the bolt threads.***

***Install the sensor with the cable exiting towards the nearest pole.***

5. Attach the assembly to the square torque tube using the sandwich plate (#16091), 7" stainless bolts (#17245), and nuts (#16101).
6. Check that the pyranometer is at the correct angle along both axes. Adjust if necessary and tighten all bolts and nuts to secure.



***It is critical that the pyranometer be at the same angle/level as the PV panels.***

***If possible, level the array table and then install the sensor, taking care that the pyranometer mount is at the same level as the PV panels.***



## Pyranometer Mount #16073 | Square Torque Tube


**Additional Configurations**

Pyranometer Mount #15845 can be assembled in several ways for more adjustability. Reverse Plane of Array (RPOA; not shown) is also possible, as Universal Mounting Bracket #15498 is identical on both faces.



*When used for RPOA, the white sun shield should be removed and the sensor cable should exit along the array torque tube, typically north or south.*

“Z” Configuration (shown in assembly diagram)



“T” Configuration (to reduce sensor height)

